










I push the tap with a 1mm pin


















14

2mm



15





16

Piston must move in both directions

